



FIG. 1









FIG. 3A



**FIG. 4** 






FIG. 5A





WIRING DIAGRAM OVERMOLD NOT SHOWN FOR CLARITY

FIG. 6A








FIG. 6B












FIG. 90